Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

JJ1329 SOIL NY Spills S118460703
ENE 2370 EAST 19TH STREET N/A

ENE 2370 EAST 19TH STREET > 1 BROOKLYN, NY

1.692 mi.

8934 ft. Site 3 of 3 in cluster JJ

Relative: SPILLS: Higher Name: SOIL

Actual: Address: 2370 EAST 19TH STREET

17 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 1509623 / 2016-06-08

 Facility ID:
 1509623

 Facility Type:
 ER

 DER Facility ID:
 319777

 Site ID:
 520258

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: D4 2401 SWIS: Spill Date: 2015-12-22 Investigator: **RMPIPER** Referred To: Not reported Reported to Dept: 2015-12-22 CID: Not reported Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Pote Falsard In Computer: 2015 13 23

Date Entered In Computer: 2015-12-22
Spill Record Last Update: 2016-06-08
Spiller Name: SAL
Spiller Company: SCHINDLER

Spiller Address: 2370 EAST 19TH STREET

Spiller Company: 999 Contact Name: SAL

DEC Memo: "12/22/15: J.Kann - spoke with Sal Saieva of the Postal Service. He

said that an elevator contractor was at the site performing a drop test and noticed that there was some oil loss. It is not clear yet if the elevator has a double hulled jack and if there was a release to the environment. An environmental contractor will be coming to the site to collect soil samples either later tonight or tomorrow am. Sal was instructed to test for TPH given the possible contaminant is mineral oil. The elevator (car) has been shutdown for now to prevent

any additional release. CSL to be prepared and sent to Sal Saieva US Postal Service 1050 Forbell Street, Room 2090 Brooklyn, NY 11256 12/29/15: J.Kann - CSL prepared and sent out. As per Jeff the

analytical method required for sampling was EPA Modified Method 8100 because the spill was mineral oil. Spill transferred to Piper (runner on 12/22/15) 5/16/16- DEC Piper - Louis Berger has completed an investigation of the hydraulic fluid release at the USPS facility located at 2370 East 19th Street in Brooklyn, NY. Mr. Saieva with the USPS informed Louis Berger that approximately 80 gallons of hydraulic

fluid was lost during the spill. During the investigation,

approximately 80 gallons were recovered. Approximately 40 gallons were recovered from the elevator piston and another 40 gallons were

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Database(s) EPA ID Number

recovered from the pit that housed the elevator piston. The elevator shaft floor was observed to be in good condition and constructed out of concrete. No cracks were observed. The pit housing the elevator piston was observed to extend approximately 16 feet below the shaft floor. This pit was observed to be cased in steel and had a steel bottom. It appears that most of the fluid that was lost was contained within this pit. Louis Berger is currently awaiting documentation from USPS that shows how much hydraulic fluid was used and how much was recovered. 6/8/16- DEC Piper- Based on work to date, this spill is closed. See dec docs for report. "

"unsure if there is a spill possible equipment failure Tomorrow they

will investigate"

All Materials:

Remarks:

520258 Site ID: Operable Unit ID: 1269299 Operable Unit: 01 Material ID: 2273315 Material Code: 2630 Material Name: mineral oil Case No.: Not reported Material FA: Petroleum Quantity: Not reported Units: Not reported Recovered: Not reported Not reported Oxygenate:

EDR ID Number